

DRAFT

Materials Management Plan Interstate-70 Open Channel Drainage aka Montclair Creek

July 2014

Prepared for: U.S. Environmental Protection Agency 1595 Wynkoop St Denver, CO 80202



City and County of Denver Department of Environmental Health Environmental Quality Division 200 West 14th Avenue, Department 310 Denver, Colorado 80204 720-865-5439

Contents

1.0 Introduction	. 4
1.1 Site History and Description	. 5
1.2 Potential Risk from Subsurface Contaminants at the Site	. 5
2.0 Materials Management Plan Goals	
2.1 Proper Management of Exposed Subsurface Material.	. 7
3.0 Affected Activities and Responsible Personnel	
3.1 Affected Activities	. 7
3.2 Responsible Personnel	
3.2.1 Program Monitor	. 8
3.2.2 Work Supervisor	
3.2.3 Field Materials Management Representative/Environmental Representative	10
3.2.4 Record Keeping	
4.0 Excavation Procedures.	11
4.1 Work Site Photograph Documentation	
4.2 Observation of Special Conditions During Excavation.	
4.3 Solid Material/Waste Management.	. 2
4.4 Screening and Assessment of Waste	. 4
4.4.1 PID Readings	
4.4.2 CGI Readings	. 4
4.4.3 Containers and Other Unidentified Items	
4.4.4 Soil Characterization	
4.5 Liquid Waste Management	
4.6. Methane Detection and Mitigation	. 7
4.7 Reduction of Contaminant Spread	. 9

Appendices

A CCOD Asbestos Standard Operating Procedures

Figures

1 Project Area

Acronyms

ASARCO American Smelting and Refining Company

AOC Administrative Order on Consent
CDOT Colorado Department of Transportation

CDPHE Colorado Department of Public Health and Environment

CFR Code of Federal Regulations LDR Land Disposal Restrictions MMP Materials Management Plan

OSHA Occupational Safety and Health Administration

OU 2 Operable Unit 2

OVA-FID Organic Vapor Analyzer-Flame Ionization Detector

ppm parts per million

RI/FS Remedial Investigation/Feasibility Study

USEPA United States Environmental Protection Agency VB/I-70 Vasquez Boulevard/Interstate-70 Superfund Site

Formatted: Footer distance from edge: 0.3"

1.0 Introduction

This Materials Management Plan has been developed by CTL/Thompson, Inc. (CTL) and the City and County of Denver (the "City") to outline preventive measures and guidelines for managing subsurface materials associated with the construction of the proposed open channel drainage (the "Project"). The Project—Portion of will go through the Denver Coliseum—and Globeville Landing Park, which are located within Operable Unit Number 2 ("OU 2") of the Vasquez Boulevard/Interstate 70 ("VB/I-70") Superfund Site.

The Denver Coliseum parking lot is also constructed over an unpermitted landfill, which is believed to encroach into at least the north portion of the Globeville Landing Park. These properties are owned by the City.

Because the exact boundaries of the landfill are uncertain, this MMP will apply to the entire Project. The Project starts at the south side of the Coliseum building and will follow the contours of McFarland Drive around the southern edge of the parking lot until Arkins Court, at which time there will be a turn to the left, cutting through Globeville Landing Park to the river just north of the existing outfall. The channel will be "naturally" engineered approximately 10 feet deep and 140 feet wide. Figure 1 shows the approximate alignment of the Project.

This MMP contains guidelines in <u>general</u> conformance with applicable regulatory statutes and procedures.

It should be noted that the document <u>Wastewater Capital Projects Management</u> Standard Construction Specification – 14.0 Removal and Disposal of Construction <u>Debris and Contaminated Materials</u>, is to be used in conjunction with this MMP. However, the following Sections of the Specification conflict with this MMP, and thus are waived or an explanation provided as follows:

- 14.0.3 Environmental Consultant: This indicates that the City and County of Denver shall have an Environmental Consultant under contract. This section is considered waived and it is the responsibility of the Contractor to provide at least one Field Materials Management Representative for oversight during work performed for the Project, and this is discussed further in this MMP
- 14.0.5 Submittal (OSHA Requirements): This indicates in #6 that Disposal Profile Sampling is to be performed. While this is generally true if new wastes are encountered, some waste disposal profiling has already occurred and, this is discussed further in this MMP.
- 14.0.7.1 Removal: Discusses additional removal and inspection of contaminated materials; this section is waived.
- 14.0.7.3 Confirmation Sampling: #1 is waived because the Contractor is not expected to "chase" contamination and confirm full cleanup. #2 is still

applicable in that a Sampling and Analysis Plan is still necessary, in the event that sampling is needed for new waste profiles or other reasons.

- 14.0.7.4 Field Testing: #4 is waived, again with the reasoning that responsible management of contaminated materials encountered is the expectation, but that chasing contaminants and confirming cleanup are not.
- 14.0.7.4 Protection of Storm and Sanitary Sewers: is deleted in full.

1.1 Site History and Description

This project is located near the original location of the Omaha & Grant Smelter, which was built in 1882 and operated until 1902. The Omaha & Grant Smelter facility was built on approximately 50 acres bordering the South Platte River located south of Interstate 70 and south of the existing Denver Coliseum. The smelter was closed in 1903 and the smelter buildings were subsequently demolished.

Over the years, the City gradually acquired and sold parcels of land that had formerly been used for various aspects of smelter operations. The land beneath the Coliseum was used as a dump site, presumably during the first half of the century and prior to any environmental permitting requirements. The Coliseum was then constructed in the early 1950s.

1.2 Potential Risk from Subsurface Contaminants at the Site

The USEPA's findings concerning the VB/I-70 site identify the contaminants of concern ("COCs") as Lead and Arsenic from the former smelting operations. These findings have been corroborated through field investigations performed in the vicinity by the Colorado Department of Transportation ("CDOT") and Pepsi Bottling Group. These investigations are extensive and difficult to encapsulate in this document, so we instead have summarized recent studies that are specific to the Project, below.

Brown and Caldwell and CTL conducted soil and ground water studies in 2010 and 2011. These studies focused on soil and ground water sampling via drilling, and revealed similar findings. The findings included the following contaminants, particularly in the landfill area beneath the Coliseum parking lot:

- Landfill debris, including asbestos and Polynuclear Aromatic Hydro
 - carbons (PAHs) in soil;
- Methane gas;
- Petroleum hydrocarbons in soil;
- Arsenic and Lead in the soil;
- Arsenic, Cadmium, Iron and Manganese in the ground water; and,
- Chlorinated solvents in the ground water

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Indent: Left: 0", Space After: 0

Formatted: Space After: 0 pt

Formatted: Indent: Left: 0.5", Hanging: 0.5", Space After: 0 pt, Bulleted + Level: 1 + Aligned at: 0.25" + Indent at: 0.5"

Formatted: Indent: Left: 1", Space After: 0 pt, No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Space After: 0 pt, Bulleted + Level: 1 + Aligned at: 0.25" + Indent at: 0.5"

Formatted: Indent: Left: 0.5", Hanging: 0.5", Space After: 0 pt

Test pits were also performed in the Coliseum parking lot by CTL in May 2013, as drilling can be limited or inconclusive when evaluating and planning for asbestos. The five (5) test pits revealed friable asbestos in each pit.

Formatted: Indent: Left: 0", Space After: 0

Four (4) additional borings were advanced by CTL in September 2013, solely for the purpose of characterizing the soils along the alignment for proper waste disposal. This study focused on the alignment above the landfill, as a Waste Management representative had indicated that they had sufficient information from the landfill area and that the higher-segments of the project closer to the surface were not as well characterized. —Soils from each boring were homogenized and analyzed via the Toxicity Characteristic Leaching Procedure (TCLP) for Lead, Arsenic and Chromium, to determine if the leachable component of these metals would be high enough to be classified as "hazardous", and therefore require disposal at a hazardous waste (Subtitle C) landfill. The results of our borings indicate that, when averaged as one waste stream, the TCLP concentrations of the soil were within non-hazardous concentrations, and are expected to be approved for disposal at a Subtitle D landfill.

Formatted: Space After: 0 pt

Although <u>waste management site workers are is</u> considered to be the primary focus of this MMP, guidelines are also included for the protection of <u>workers and</u> work-site visitors who may potentially be exposed to contaminants from the Project. <u>More specific details for worker protection, such as use of respirators and other PPE, emergency contacts, evacuation procedures, and other details can be found in the <u>site-specific Health & Safety Plan prepared by the Contractor. Work-site visitors are considered to be those people who have job-related reasons for being in close proximity to the work site. This MMP is not intended to provide guidelines for the protection of the public in general, or people who may be in close proximity to the work-site for reasons that are not job-related.</u></u>

Formatted: Space Before: 0 pt

2.0 Materials Management Plan Goals

The goals of this Materials Management Plan are:

To provide guidelines to prevent unnecessary contact with, and spread of, site workers and work site visitors from coming into contact with potentially contaminated subsurface materials such as soils and former smelter materials, demolished building foundations, debris, and methane. Asbestos is also expected to be encountered and is discussed in the City of Denver Standard Operating Procedures which is included as Appendix A to this MMP. The City of Denver Standard Operating Procedures (SOP) for asbestos in soils is included by reference as an integral part of this MMP.

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

To facilitate the proper management and disposal of exposed and excavated soils, debris, and former smelter materials.

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", No bullets or

2.1 Proper Management of Exposed Subsurface Material

The Project will disrupt the surface cover of sod and pavement (sometimes referred to as "caps and barriers") at the Site. Subsurface materials brought to the surface will need to be handled appropriately to maintain a safe work environment and ensure that any smelter-related or other chemicals which may be present will not spread to other media.

Worker and work-site visitor health and safety guidelines and requirements are the responsibility of the Operator/Contractor performing the intrusive work. The Typically, the Operator Contractor will develop and adhere to a Health and Safety Plan developed for the Site and work being performed. The plan will comply with Occupational Safety and Health Administration (OSHA) regulations, 29 Code of Federal Regulations (CFR) 1910.120. In addition, the Operator Contractor, as part of Performing performing processes for excavation, will be required to describe cedures to be used to address dust, erosion and sediment control for the Project.

3.0 Affected Activities and Responsible Personnel

For the purpose of this MMP, the "Project" is defined as all privately-owned and City-owned property that will be disturbed by installation of the Phase 2 High Street Outfall Storm Sewer. All activities within the Project shall be subject to the conditions and requirements of this MMP. These activities are expected to be performed by City Operating Divisions (such as Parks and Recreation, and Public Works), and/or outside contractors (these entities are referred to generically as "Operators" in this Plan). In the sections that follow, examples of the types of intrusive activities that can be performed by these Operators are discussed, as well as the titles and responsibilities of key personnel.

3.1 Affected Activities

Any intrusive work to be performed for the Project must follow proper City permitting procedures and the requirements and procedures of this MMP. For the purpose of this MMP, intrusive work is defined as any and all activities that result in penetration of the existing caps and barriers and can include the following activities:

- Any excavation below grade.
- Pavement removal/replacement.
- Compaction grouting / concrete injection
- Utility cuts (municipal, private services or contractor), including but not limited to the following:
 - <u>Irrigation lines and other appurtenances in Globeville Landing Park</u> (City of Denver)

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Space Before: 0 pt. After: 0 pt

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

- · Water (Denver Water)
- Natural Gas (Xcel Energy)
- Electric (Xcel Energy)
- Steam (Xcel Energy)
- Telephone (Qwest, AT&T, MCI, etc.)
- Cable television (AT&T, etc.)
- Sanitary sewer (City of Denver)
- Storm sewer (City of Denver)
- New service/repair/modification
- Traffic control cuts (e.g. signal poles, sensor devices, etc.).
- Routine curb and gutter removal/replacement.
- Accidental or catastrophic damage to pavement or curb and gutter as a result of human error or act of God.
- Park maintenance below the existing sod.
- Emergency response activities related to any or all of the above.

3.2 Responsible Personnel

The following sections describe the titles and responsibilities of key personnel who oversee and implement this Materials Management Plan.

All workers directly involved with trenching, or construction within the trench, must have 40 hours of OSHA general training and 8 hours of supervisor training in accordance with 29 CFR 1910.120 ("Hazardous Waste Operations and Emergency Response")

3.2.1 Program Administrator

The Program Administrator shall be a person in the Environmental Services Division of the City and County of Denver's Department of Environmental Health, as appointed by the Director of Environmental Services or the Director's designated representative. The Program Administrator shall have appropriate safety training and experience in accordance with OSHA Regulation 29 CFR 1910.120 "Hazardous Waste Operations and Emergency Response" paragraph (e)(1) "Management and supervisor training", and shall be the individual who is responsible for special permits determinations (Section 1.0) and coordination of the MMP components.

3.2.12 Program Monitor

The Program Monitor shall be a designated person of the outside contractor in the Department of Environmental Health-who monitors the public health issues associated with the Management Planthis MMP, acts as a liaison with regulatory entities on regulatory matters, serves as a point of contact for employee concerns related to risks to individual workers, and handles public inquiries regarding health concerns related to the Site. This person may or may not be the contractor's existing, in-house Health and Safety Officer.

Formatted: Indent: Left: 1", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25", Tab stops: Not at 0.25"

Formatted: Indent: Left: 1", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25", Tab stops: 1.25", List tab + Not at 0.25"

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Space Before: 0 pt, After: 0 pt



3.2.3 Division Coordinators

Division Coordinators are the day-to-day representatives for each City Operational Division or public utility. These individuals will verify the proper implementation of the Management Plan for projects conducted at the Site under the charge of their division and serve as points of contact when anomalous conditions are encountered in the field. In addition, the Division Coordinators will coordinate work efforts among all relevant City divisions and departments, utilities and/or outside contractors. The Division Coordinators, by combination of education, work experience, and supplementary training shall be uniquely qualified to:

Identify and administer special requirements for performance of work activities at the Site.

 Have working knowledge of activities conducted by or under the auspices of various City Departments (to include those activities conducted by private utilities and outside contractors). Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Indent: Left: -0.25", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Specific duties of the Division Coordinators include: Verify and document that all appropriate individuals and Work Supervisors Formatted: No bullets or numbering have reviewed this MMP and fully understand its contents and required procedures. Collect and consolidate all applicable job site compliance forms, such as Worker Affidavits, Health and Safety Plan, and Worker Exposure Records, received from the project Work Supervisor and forward this information to the Program Administrator. 3.2.24 Work Supervisor Formatted: Space Before: 0 pt, After: 0 pt Job site compliance with the requirements of this MMP rests with the Work Supervisor. The Work Supervisor will -be an employee of the outside contractor. Specific responsibilities of the Work Supervisor include: Formatted: No bullets or numbering Compliance with this MMP. Formatted: Indent: Left: 0.5", Hanging: 0.5", Line spacing: 1.5 lines, Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: Communication of the requirements of this MMP to the work crew. Providing a brief informational presentation to all members of the assigned work crew. Comment [DH1]: One time? Daily? Formatted: Indent: Left: 1", Line spacing: Forwarding applicable job site compliance records to the Program 1.5 lines, No bullets or numbering Monitor Division Coordinator. Formatted: Indent: Left: 0.5", Hanging: 0.5", Accordingly, the Work Supervisor must have working knowledge of the activities Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25" performed by various City Departments, public utilities, and outside contractors Comment [DH2]: How frequently? 3.2.35 Field Materials Management Representative/Environmental Representative Formatted: Space Before: 0 pt, After: 0 pt The outside contractor City shall also appoint or retain at least one Field Materials Comment [DH3]: I'm not seeing a relationship that ties the outside contractor back to the city and Management Representative for oversight during work performed for the Project. holds them accountable This person can also be known as the Environmental Representative or Environmental Professional, and may or may not be qualified to perform the asbestos consulting and oversight duties as described in the Denver SOP (Appendix A). The Field Materials Management Representative(s) shall have the authority to: Oversee work activities relating to the proper management of exposed <--Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab -subsurface materials. after: 0.25" + Indent at: 0.25" Stop operations when conditions change to ensure that materials Formatted: Indent: Left: 1", Line spacing: 1.5 lines, No bullets or numbering management procedures are adequate. Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab The Field Materials Management Representative, by a combination of education, after: 0.25" + Indent at: 0.25" work experience, and supplementary training shall have the following minimum Formatted: Indent: Left: 1", No bullets or qualifications: Formatted: Indent: Left: 0.5"

An associate degree or t<u>T</u>wo or more years of <u>experience study in the</u> physical sciences, engineering,

or a health-related field.

 Completion of 40-hours of OSHA general training and 8-hours of supervisor training-in accordance with 29 CFR 1910.120 ("Hazardous Waste Operations and Emergency Response") and possession of certification thereto, including annual

maintenance of certification.

Participation and certification of Medical Monitoring in accordance with
 29 CFR 1910.120.

The responsibilities of the Field Materials Management Representative are:

Oversight sufficient to ensure proper management of excavated
 materials.

To compile written documentation of all material handling and disposidispose-

tion. This information shall be maintained by the contractorin Department of Environmental Health files with duplicate copies provided to the Program Administrator.

3.2.4 Record Keeping

The Program Administrator and Program Monitor shall maintain complete file documentation of all environmental, health, and safety activities conducted on the Site. Examples of documentation include Work Orders, Special Conditions Forms/Permits, Worker Affidavits, Site Monitoring Records, Worker Exposure Records, daily records of the Field Materials Management Representative, Laboratory results of debris and media encountered during the project, and Hazardous-Waste Disposal Manifests.

4.0 Excavation Procedures

This Section discusses the following:

Material/Waste management methods and procedures for managing and/or disposing of excavated materials, any produced groundwater,
 and preventing contaminant spread.

 Decontamination procedures for personnel, sample equipment, and heavy equipment.

It shall be the responsibility of the Operator to prepare a Site-specific Health and Safety Plan (HASP). A HASP is typically required when proposed work activities are

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", Line spacing: 1.5 lines, No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", Line spacing: 1.5 lines, No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5"

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", Line spacing: 1.5 lines, No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Space Before: 0 pt, After: 0 pt

Formatted: Font: Book Antiqua, 11 pt

Formatted: Normal

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0" + Tab after: 0.25" + Indent at: 0.25"

likely to encounter contaminated <u>soil</u>, ground water or smelter-related waste.


Compliance with the health and safety plan will be the sole responsibility of the Operator (outside contractor). It will also be the responsibility of the Operator to ensure that all workers assigned to the permitted work effort have received adequate training in accordance with 29 CFR 1910.120.

Comment [DH4]: This terminology is inconsistent with earlier in the plan

Comment [DH5]: This is the correct terminology

The Work Supervisor shall provide a brief informational presentation to all members of the assigned work crew prior to work initiation discussing the major aspects of this MMP, specifically the reasons for the procedure, operational considerations, and materials handling procedures.

The Field Materials Management Representative (Field Rep) makes pserve and document all field activities through and including disposition (real from the job site) of materials encountered. The Field Rep shall have the authorities and responsibilities as defined in Section 3.2.35 of this document.



to collect additional samples for <u>clarification</u> <u>determination</u> of proper health and safety requirements <u>during the project</u>.

4.3 Solid Material/Waste Management

Until otherwise amended, this This MMP assumes that much of the all-excavated material will be disposed of site; however, soils away from the Denver Coliseum parking lot, if de appropriate by the Field Rep., may potentially be and not-re-used onsite. As discussed previously, beased on sampling activity to date, most if not all of the disposed excavated-material is expected to be disposed off-site at a Subtitle D (non-hazardous) landfill, planned to be such as the Denver Arapahoe Disposal Site (DADS) operated by Waste Management. At this time, waste profiles have not yet been completed and approved by Waste Management, so this will need to occur before these assumptions are confirmed, it is not assumed that any quantity of excavated material will require disposal at a Subtitle C (hazardous) landfill. Excavated material is expected to include, but not be limited to, any of the following items:

- Native sand, silt, clay, and bedrock;
- Dark stained soils, potentially containing chemical contaminants
 - as petroleum compounds or coal based fill;
- Construction and demolition debris such as concrete, wood, and brick;
- Suspect or confirmed asbestos type building debris, such as transite.
 - -insulation, plaster, floor tile, or roofing (see Appendix A SOP);
- Dumped items such as bottles, cans, tires, newspaper, clothes; and/or,
- Smelting waste such as slag

One of the roles of the onsite field representative Field Rep will be to assist in the management and designation of the waste. The Field Reprepresentative may periodically request work stoppage to better identify soils or debris. The waste is not expected to be homogenous, so it is unlikely that there will be loads that can be considered, as an example, 100% concrete rubble (which might otherwise carry a potentially lower disposal fee). The City and County of Denver - Department of Environmental Health (DEH) has obtained approval from DADS for three waste disposal profiles. Waste will generally be loaded out under one of the following six-categories / waste profiles, as follows:

*1. Landfill material - with friable asbestos - Profile 113898CO

Formatted: Indent: Left: 0.5", Hanging: 0.5", Line spacing: 1.5 lines, Numbered + Level: 1 + Numbering Style: 1, 2, 3, ... + Start at: 1 + Alignment: Left + Aligned at: 0.25" +

Indent at: 0.5"

Formatted: Heading 2



Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0.25" + Indent at: 0.5"

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0.25" · Indent at: 0.5"

Formatted: Indent: Left: 1", No bullets or numbering

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0.25" + Indent at: 0.5"

L. Farrell Page 2 7/24/2014

 Soil with metals contamination Debris with likely chemical waste, with non-friable asbestos;

2. – no asbestos – Profile 114005CO

Railroad ties

- Debris with likely chemical waste, with friable asbestos;
- Debris with likely chemical waste, with non-friable asbestos;
- •3. Profile 114003CO
- 4. Construction debris <u>No profile needed</u>, provided it is typical construction debris, with no asbestos nor chemical or metals contamination

There will be a total of sixmay be additional waste profiles created during the project, if for example, the Field Rep observes new waste items, and after segregating and sampling, finds that the waste is significantly different to qualify as a new waste stream. In the event that new waste items or characteristics are uncovered, the City and County of Denver Public Works Project Manager should be contacted. In addition, DEH should be notified for possible assistance in the creation of new profiles., one for each category that will be approved prior to commencement of the project.

It is assumed, based on test pit information, that the vast majority of soils in the Coliseum/Landfill Area will be handled and disposed under #1 - Landfill material - with friable asbestos. The possibility of encountering asbestos within the areas away from the Coliseum is at this time considered much less likely, but possible. No new profiles are expected to be created unless the representative observes characteristics or features that are sufficiently different from what has thus far been documented, to warrant a new profile. The Field Representative will use a Photoionization Detector (PID) and be experienced at using olfactory and visual cues to identify chemical contaminants such as petroleum impacts, TCE/PCE, coal ash (commonly synonymous with PAHs), and slag.

Again, refer to Appendix A for proper identification, loading, monitoring, and packaging of asbestos waste. Generally speaking, stockpiling of asbestos - contaminated soils (ACS) is to be avoided; ACS should be excavated only when all necessary abatement crews, trucks, and other equipment are available for direct load and immediate disposal.

It should be noted that DADS shall be given 4 weeks prior to commencement of excavation, because preparations will need to be made at the landfill. This is because the presence of chemical and asbestos

L. Farrell Page 3 7/24/2014

-- Formatted: No bullets or numbering



contaminants together is atypical, and requires placement of this waste in a pre-designated area within the lined area of the landfill.

Page 4

L. Farrell

4.4 Screening and Assessment of Waste The Field Rep will use a Photoionization Detector (PID) and Combustible Gas Formatted: Left Indicator (CGI) and be experienced at using olfactory and visual cues to identify chemical contaminants such as petroleum impacts, TCE/PCE, coal ash (commonly synonymous with PAHs), and slag. Prior to beginning excavation, the contractor will provide 6-mil polyethylene lined Formatted: Font: Arial roll-off containers, with covers, for short-term stockpiling of soils and wastes. A Formatted: Font: Arial dedicated lined and covered container will be used if the Field Rep believes that Formatted: Font: Arial the waste appears different or is not otherwise appropriate for direct load into a truck under pre-approved waste profile. This scenario is expected to become more prevalent away from the Coliseum, where there is expected to be more interpretation by the Field Rep as to the nature of the waste. Each container will Formatted: Font: Arial be covered at the end of each work day. The contractor will provide an adequate number of roll-off containers to avoid down time. Formatted: Font: Arial The Field Rep will observe the excavation and may at times request the Formatted: Font: Arial excavator to place waste materials into a lined container, or on bermed, 6-mil Formatted: Font: Arial polyethylene sheeting (both types of temporary containment should be available) for waste characterization. In addition, the Field Rep will monitor the ambient air Formatted: Font: Arial near the excavator bucket using a PID and CGI Formatted: Font: Arial Formatted: Font: Arial Formatted: Font: Arial 4.4.1 PID Readings Formatted: Heading 3, Left, Tab stops: Not at 0.5" + 2" PID readings less than 10 ppm are not unusual and can be indicative of vehicle Formatted: Left exhaust and other factors, so low PID readings alone should be interpreted with some discretion by the Field Rep. This MMP does not state a threshold where action should be taken based on PID readings. The PID readings and site conditions will be taken into account together by the Field Rep in making interpretations as to whether air conditions are potentially hazardous. Formatted: Heading 3, Left, Tab stops: Not at 0.5" + 2" 4.4.2 CGI Readings Formatted: Left If greater than 10 percent of the lower explosive limit (LEL) is measured at any Formatted: Font: Arial time, (0.5% Methane) the work area will be evacuated and work practices will be Formatted: Font: Arial re-evaluated. Work will not resume until the ambient air contains less than 10% of the LEL. See Section 4.6 on Methane Mitigation. Formatted: Font: Arial

7/24/2014

2016-010025-0000517

.3 Cont	tainers and Other Unidentified Items		Formatted: Heading 3, Left, Tab stops: Not at 0.5" + 2"
		«\	Formatted: Font: Arial
ms, con	ntainers, explosives, medical waste, and other special items may be		Formatted: Left
	d. If any such items are encountered within the excavation, a multiple	was not not to	Formatted: Font: Arial
) assess	sment will be performed:	X MOODE SAN TO	
		٠	Formatted: Font: Arial
1.	The Field Rep will assess containers, in-situ, for likely chemical		Formatted: Left, Indent: Left: 0.5", Hangir
***************************************	content based on labeling, container type/shape, observation of	The same	0.5"
	contents, etc. Potentially contaminated soils will be assessed	· //	Formatted: Font: 12 pt, Not Bold
	based on nearby chemical containers, if present, or based on field		Formatted: Font: 12 pt, Not Bold
	screening observations.		Formatted: Font: 12 pt, Not Bold
		4	Formatted: Font: 12 pt, Not Bold
2	The Field Rep will otherwise attempt to identify, if possible, the	al in	Formatted: Indent: Left: 1", No bullets or
	nature of the item, whether it appears to be medical waste, a piece	1	numbering
	of machinery from smelting or other industrial operations,	``	Formatted
	ammunition, or other item.		Formatted: Font: 12 pt, Not Bold
2	The Field Den will use a DID and COLds are source problems of the	*	Formatted
3	The Field Rep will use a PID and CGI to measure ambient air at (or as close as safely possible) the location for volatiles and		Formatted: Font: 12 pt, Not Bold
	combustible gases.	1	Formatted
	combustible gases.	, market to	Formatted: Font: (Default) Arial
	A		Formatted: Font: 12 pt, Not Bold
4.	The container or item will be observed for crystallization or other)	~~~~	Formatted
***************************************	(evidence of reactively unstable materials. Reactively unstable)		Formatted
	(materials are considered unlikely, but if present, they will not be)	100	Formatted: Font: 12 pt, Not Bold
	moved until they can be chemically or physically stabilized.	was your year man or	Comment [DH6]: shouldnt ammo/UXO get
	A	*	Formatted: Font: 12 pt, Not Bold
<u>5.</u>	If the condition of a container or item can be assessed in place, the	and the	Formatted
	Field Rep will note the condition of the object, evidence of releases,		Formatted
	etc. If a container appears to be actively leaking, it will not be	Ser 1	Formatted: Font: 12 pt, Not Bold
	removed until a suitable overpack container is available for	1,1	Formatted: Font: 12 pt, Not Bold
	containment.)	į	Σ
	.		Formatted: Font: 12 pt, Not Bold
6	Sampling may be required by the Field Rep if, after instrument	*****	Formatted: Font: (Default) Arial
<u>6.</u>	readings, observation, and other factors, the Field Rep determines	The state of	Formatted
	that he/she can obtain a sample safely.	Ì	Formatted
	and the one dan obtain a dample dately.	*	Formatted: Font: 12 pt, Not Bold
7.	The Field Rep will observe and document whether releases, if any,		Formatted
	appear likely to have impacted soils or other wastes around or		Formatted
	below the container or item. If a suspected release has occurred,	**	Formatted: Font: 12 pt, Not Bold
	the extent of the release will be assessed by excavating around the	2 000°00 7000 5000 5000 5000 500	Formatted: Font: 12 pt, Not Bold
	point of the release. Where contaminated soils are observed, it will	- M. W. W. W. W.	Comment [DH7]: even if this means chasing
		a second was mad now as	Formatted: Font: 12 pt, Not Bold

L. Farrell Page 5 7/24/2014

(located physically above or adjacent to the location of the observed contamination, regardless of the presence of visible leakage from each container.) Formatted: Indent: Left: 1", No numbering Formatted: Indent: Left: 0.5", Numbering Formatted: Indent: Left: 1", No numbering Formatted: Indent: Left: 1", No numbering Formatted: Indent: Left: 1", No numbering 1, 2, 3, + Start at: 1 + Alignment	bullets or
each container. Formatted: Indent: Left: 0.5", Ha 0.5", Numbered + Level: 1 + Numb 1.2, 3, + Start at: 1 + Alignmen	
0.5", Numbered + Level: 1 + Numbered + Level: 1 + Alignmen	
1, 2, 3, + Start at: 1 + Alignmen	
O The leastion will be managered from a fixed reference point and at Alichatet, 0.35% a Tadant at 0.55	
8. The location will be measured from a fixed reference point and plotted on a scaled drawing; if it is practical, the location will be	
Detween Lauri and Asian text, Don	
Marked in the field with flagging or stakes. space between Asian text and num Alignment: Baseline	pers, Font
Formatted: Font: (Default) Arial	
9. The Field Rep will take photograph(s) documenting the location and Formatted: Font: 12 pt, Not Bold	
general condition of the feature: Formatted: Indent: Left: 1", No	bullets or
numbering	
10. If in the judgment of the Field Rep, the container or other item can Formatted: Font: 12 pt, Not Bold	
be moved safely, the Field Rep will request the excavator to place "Formatted: Indent: Left: 0.5", Ha	
1, 2, 3, + Start at: 1 + Alignmen	nt: Left +
collaborative effort, and if the item remains unknown with the potential to release a hazardous or petroleum substance other allow hanging punctuation, Don't a	
position personnel chauld be apposited to determine if there are	t adjust
	bers, Font
is it is formatted: Font: 12 pt, Not Bold	-
Formatted: Font: 12 pt, Not Bold	
objections. If there is no consensus that the project can continue safely because of an unidentifiable container, condition, or other item, work shall stop and the Denver Department of Environmental Alignment: Baseline Formatted: Font: 12 pt, Not Bold **** **** **** **** **** **** ****	bullets or
because of an unidentifiable container, condition, or other item,	
Health shall be contacted and made aware of the situation. Formatted: Font: 12 pt, Not Bold	
Formatted: Font: 12 pt, Not Bold	
12. Containers and other special items will be segregated based on Formatted: Font: 12 pt, Not Bold	
general waste types, media, and waste disposal requirements (e.g., Petroleum contaminated soil, would be segregated into a separate	
stockpile from soils excavated below a leaking drum of chlorinated	
solvent).	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
13. Waste Management may need to be contacted when encountering * " Formatted: Font: 12 pt, Not Bold	
unknown items, for guidance on characterizing and segregating	
items for disposal. Formatted: Font: 12 pt, Not Bold	
Formatted: Font: (Default) Arial	
14. At no time shall unknown containers or other items, that are sealed Formatted	
and have the potential to contain a hazardous substance or create a hazardous condition, be assumed to be non-hazardous and	
combined with soil or non-hazardous debris to be disposed.	
Formatted	()
Formatted: Font: 12 pt, Not Bold	
Soil Characterization Formatted: Indent: Left: 0"	
Formatted	
Formatted: Font: Book Antiqua, 1	1 pt, Bold

7/24/2014

Page 6

L. Farrell

Asbestos wastes will be managed per the SOP. Soils impacted with petroleum, solvents, slag, and/or coal ash are assumed prior to bid to be profiled for non - hazardous disposal at DADS. Therefore the Field Rep is not expected to stop work for laboratory analysis when these types of soils are encountered, unless in his/her judgment the chemical encountered is sufficiently concentrated (e.g. free product) or different that additional observation or characterization is warranted.

Formatted: Font: (Default) Arial
Formatted: Left
Formatted: Font: Arial
Formatted: Font: Arial

All necessary field-based characterization and laboratory analyses will be performed by the contractor and a qualified environmental laboratory. Laboratory analysis and followup landfill approval can take up to 5 days total, and the Contractor should prepare for instances where a lined container must remain on the project while the excavation continues.

Formatted: Font: Not Bold, Not Italic

Formatted: Font: Arial

4.54 Liquid Waste Management

Ground water is expected to be encountered in the lower half of the Project. Dewatering will be necessary and this is permitted through the Colorado Department of Public Health & Environment (CDPHE). The City currently maintains a Remediation Activities Discharging to Surface Water Permit. This permit will be transferred to the contractor once a contractor has been selected. The contractor shall be familiar with the permit and be prepared to treat for metals, solvents, and other parameters that are expected to be required per the permit. The contractor will plan for and be familiar with the dewatering operation, which is expected to involve pumping into frac tanks, onsite treat ment, periodic sampling and analysis, and discharge into a storm sewer.

It is not expected that liquid wastes will require significant treatment or management beyond what is required in the CDPHE permit, nor require hauling or disposal offsite. Soil that is saturated with ground water is expected to contain low levels of chlorinated solvent; however, a DADS representative has indicated that the concentrations, particularly after distributed into soils, are assumed to be negligible and subject to volatization, and thus not required to have further management or waste profiling unless new information comes to light during the Project.

4.65. Methane Detection and Mitigation

Methane is an odorless gas which is a byproduct of decomposing organic matter. It is lighter than air, and dissipates in the open air, but presents an explosive hazard at concentrations between 5% and 15% in air. A particular danger is its buildup in poorly ventilated spaces. The Lower Explosive Limit (LEL) is the concentration where there is enough methane to present an explosive hazard. For methane the "%LEL" is 5, meaning 5% methane in air is an explosive hazard.

L. Farrell Page 7 7/24/2014

(The Upper Explosive Limit (UEL) is 15%, beyond which the concentration is too "rich" to present an immediate hazard, but realistically the LEL will be encountered and responded to long before any consideration of UEL.)

When excavating within the landfill, or, at the Field Representative's discretion, near suspected landfill boundaries, methane meters shall be used. These will include a hand held device equipped with a pump, (such as a "4-gas" meter or "methanometer") and used by the Field Rep, as well as personal, clip-on type devices (such as a GP-01 manufactured by RKI Instruments) worn by at least two members of the onsite contractor(s). The amount of clip-on devices worn and numbers of subcontractors participating will be at the discretion of the Field Rep but is expected to be a minimum of 2 people deemed to be potentially most exposed or working in the most confining space at any particular time.

The Work Supervisor, the Field Rep, and contractors working in the trench will be familiar with the operation of methane meters and understand the hazards of methane. The contractor will have at least two portable, spark-proof, weather-proof fans onsite, and a power source as needed, that can be brought online quickly to dissipate methane gas. The fans should also have the ability to connect to flexible hoses which can be used to direct air down into the excavation, for rapid air displacement.

It is anticipated that the installation of the box culvert along the alignment may potentially create a "confined space" per OSHA definition. The contractor should plan for continuous ventilation of this feature during installation to avoid methane buildup.

The Field Rep shall document methane readings from all methane meters at least every 30 minutes. 10% of a threshold concentration in air is a generally accepted industrial hygiene principal and generally requires further evaluation of a hazard before proceeding. If any of the readings are over 10% of the LEL (that is, 0.50% total concentration of methane in air), the following steps shall be taken:

- Project stopped, machinery shut off, and all personnel evacuated outside -of the exposure (> 10% LEL) area.
- Work Supervisor and Project Monitor notified.
- The Supervisor and Field Rep will confer onsite and agree on appropriate steps, which may include engineering controls to dilute the methane concentration to yield below-less than 10% LEL.
- Readings shall be taken again no sooner than 10 minutes after initial exceedance was reported. If readings are below 10% LEL, work may re-commence.
- In the unlikely event that readings continue over 10% LEL even with engineering controls, the Project team shall meet and agree on appropriate next steps in writing before work re-commences. Next

Formatted: Indent: Left: 0.5", Hanging: 0.5", Bulleted + Level: 1 + Aligned at: 0.25" - Indent at: 0.5"

Comment [DH8]: do you mean "exclusion

L. Farrell Page 8 7/24/2014

steps may or may not include: installation of more permanent venting/mitigation and monitoring measures in the immediate area of the hazard, and/or excavation along a different area of the Project until mitigation measures are agreed upon and deemed effective.

Formatted: Indent: Left: 1", No buillets or numbering

Formatted: Indent: Left: 1", No buillets or numbering

Formatted: Heading 2

| Formatted: Font: (Default) Book Antiqua, 11 pt

through a variety of mechanisms which include (but are not limited to): migration of dust containing chemicals, movement of particulate matter in water, and physical removal from the site on worker's clothing, work vehicles, or other direct mechanisms. Every effort will be made by the Operator to prevent the spread of contaminated or potentially contaminated materials from the controlled area. The Operator's Site-specific Health and Safety Plan will provide guidelines to prevent the spread of contamination or potentially contaminated materials from the work area.

Decontamination procedures can be used to prevent the spread of contamination from the work area. Proper decontamination procedures for per sonnel and heavy equipment will be followed. The procedures will depend upon the level of personal protective equipment employed, and the types of materials encountered during the performance of the work. In general this will mean that personnel will wear disposable nitrile gloves and booties over their work clothing when coming into contact with known or suspected chemical contaminants.

Back-hoe buckets and other exposed components of heavy equipment will be rinsed off into the excavation where the contaminants are already inherently present, before proceeding into less-suspect areas. The need and degree of rinsing will be at the discretion of the Field Rep.

Although not anticipated to be common, the Field Rep, in rare cases (such as when dealing with a previously undocumented, hazardous type of contaminant), may request that wash-water or other materials generated during the decontamination process be properly containerized, and disposed into drums or other containers for special disposal.

Proper asbestos decontamination procedures for personnel, sample equipment, and heavy equipment are described in Appendix A.

L. Farrell Page 9 7/24/2014